

Figure 3.72. Corner break for US-64 (1) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	71
Figure 3.73. Corner break for US-64 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	72
Figure 3.74. Spalling for I-440/I-40 (1) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	73
Figure 3.75. Spalling for I-440/I-40 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	74
Figure 3.76. Spalling for US-64 (1) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	75
Figure 3.77. Spalling for US-64 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	76
Figure 3.78. Joint seal damage for I-440/I-40 (1) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	77
Figure 3.79. Joint seal damage for I-440/I-40 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	78
Figure 3.80. Joint seal damage for US-64 (1) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	79
Figure 3.81. Joint seal damage for US-64 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.....	80
Figure 3.82. PCC-PCR for I-440/I-40 (1) sections.....	84
Figure 3.83. PCC-PCR for I-440/I-40 (2) sections.....	84
Figure 3.84. PCC-PCR for US-64 (1) sections.....	85
Figure 3.85. PCC-PCR for US-64 (2) sections.....	85
Figure 3.86. Fatigue cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	89
Figure 3.87. Block cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	90
Figure 3.88. Edge cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	91
Figure 3.89. Unsealed wheel path only longitudinal cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	92
Figure 3.90. Total sealed wheel path only longitudinal cracking for three reference survey sections of AC-LTPP survey.....	92
Figure 3.91. Unsealed non-wheel path only longitudinal cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	93
Figure 3.92. Transverse cracking counts for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	94
Figure 3.93. Unsealed transverse cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	95
Figure 3.94. Total sealed transverse cracking for three reference survey sections of AC-LTPP survey.....	95
Figure 3.95. Total unsealed cracking ratings for three reference survey sections of AC-LTPP survey; (a) low, (b) moderate, (c) high, and (d) total.....	96
Figure 3.96. Rutting for three reference survey sections of AC-LTPP survey; (a) right wheel path and (b) left wheel path.....	99